



400 W. Artesia Blvd.,
Compton, CA 90220

SMITTYBILT TECHNICAL UPDATE

DATE 7-14-16

APPLICATION 2007+ JK

PART NO. 2793

TECHNICAL ISSUE

Depending on positioning of table, side brackets may slightly come into contact with tailgate if mounted on the inside of the tailgate.

CORRECTIVE ACTION

Short term fix: use M12 or ½" flat washer(qty 4) as spacer between tailgate and table.

If you need washers sent, please contact Smittybilt directly at 800-776-0767

Long term fix: revising part for future manufacturing.

EXPECTED CORRECTION TIME

Corrected. See Corrective Action (above)

14 Days 30 Days 60 Days 90 Days

REQUIRES PART NOTE IN ISIS

YES NO

NOTES:

CONTACT TECH SUPPORT
FOR FURTHER QUESTIONS:
tech@smittybilt.com (800) 776-0767

Depending on mounting location, side brackets may slightly contact tailgate when mounted on the inside of the tailgate.(fig 1) Use flat washer between tailgate and table to allow for clearance. Use one washer for each of the 4 mounting bolts. Fig 2

