



400 W. Artesia Blvd.,  
Compton, CA 90220

# SMITTYBILT TECHNICAL UPDATE

DATE

APPLICATION

PART NO.

## TECHNICAL ISSUE

The bolt securing the pivot pin may come loose.

## CORRECTIVE ACTION

Re-install pivot pin bolt using Nord Lock washers. (Shown Below) This will prevent the bolt from "backing-out"  
Current inventory now includes these.

If you are in need of some (Part #76857-04) Contact Smittybilt and we will get a set our to you right away.

1-800-776-0767  
tech@smittybilt.com

## EXPECTED CORRECTION TIME

Corrected. See Corrective Action (above)  
 14 Days  30 Days  60 Days  90 Days

## REQUIRES PART NOTE IN I S I S

YES  NO

NOTES:

CONTACT TECH SUPPORT  
FOR FURTHER QUESTIONS:  
[tech@smittybilt.com](mailto:tech@smittybilt.com) (800) 776-0767

Copy Image/s Here:

**Note:** Nord Lock Washers need to be installed with the “coarse” pitch sides facing inward towards each other and the “fine” pitch sides facing outward.

